



Bob Smeads daughter missing in airplane

May 25, 1992
Montana
1992-007

No mission summary available at this time

Additional Note: The NTSB report (SEA92FA113) indicated the the pilot probably lost control and entered a stall/spin before impacting the ground in a nearly vertical position. The pilot was not familiar with the area, nor did he have mountain flying experience. The pilot was flying toward an uphill slope which commonly causes a stall/spin with pilots who are not familiar with mountain flying.

RMRU is a volunteer search and rescue team that covers Riverside County and assists other teams with search and rescue efforts in other counties. Each member purchases their own equipment and takes time off work, without compensation, to participate in search and rescue missions. Team equipment is purchased from contributions from the community. We are a non-profit organization and are funded by [donations](#) from people like you.